Navajo Abandoned Uranium Mine

Site Screen Report

This form is for use at the site of abandoned uranium mines (AUM) located on Navajo Nation lands. Applicable sites include all mine and mine features that have or have not undergone reclamation by the Navajo Abandoned Mine Lands Reclamation Program, including features, adits, pits and waste piles. Applicable sites also include all AUM sites listed in the USEPA CERCLIS database, all sites listed in the 2008 AUM GIS Report issued by USACOE and USEPA, all AUM sites on allotment lands associated with the Navajo Nation, and any and all AUM sites not listed in any database located on Navajo lands. Reconnaissance of any sites located on lands adjacent to Navajo lands that may be impacting Navajo lands will need to be coordinated with the authorities appropriate to those lands.

The purpose of the form is to ascertain the status and location of the identified AUM site, and record all immediate site information associated with the mine site. Decisions and recommendations on what additional steps are needed will be provided on a separate document.

Paul Huskie No. 20 AUM Site

Navajo AUM Western Region

Prepared by:

Weston Solutions, Inc.

Contract: W91238-06-F-0083

12767.063.599.1111

January 2011

Part I **Site Identification, Location and Status** Site Names and ID numbers as applicable Mine ID: 383 Map ID: W68 **CERCLIS:** NNN000909104 Navajo Abandoned Mine Land Reclamation Program: None Local name / Aliases: Paul Huskie #20; Paul Huskie #1; Paul Huskie No. 1 **Chapter and local area:** Cameron Chapter County: Coconino State: Arizona **Lat/Long:** 35.7974697924 N / -111.411841263 W Nearby road and highway: Highway 89 Local Post Office: Cameron, AZ Surface Land Status: check one or more and provide ownership and contact information below **Tribal Trust Land Public lands Private Tribal Fee Land Bureau of Land Mgmt Allotment** State Fee land **Subsurface Mineral Rights:** No information on subsurface mineral rights ownership was found in the EPA/AUM Database. Claim and operator information: The mine site surface land status is classified as Tribal Trust Land. Historical documents showed the operator of the mine as the Domino Mining Company in 1959. No additional ownership / lease information was identified in the EPA/AUM database.

Estimated volume of mine waste onsite: None

Number of residential structures within 200 feet of mine: None

Part II Summary of radiological readings

Highest gamma radiation measurement:

247,089 counts per minute (cpm)

Describe any other radiological measurements:


A total of 1,648 gamma radiation measurements were collected from the mine site, ranging from 9,139 cpm to 247,089 cpm. The measurements collected at an isolated pile of petrified wood were found at a maximum level of approximately 250,000 cpm. The measurements are represented in Figures 1 and 2.

Background Readings: 14,140 cpm

Background Average: 14,140 cpm

Distribution Chart and Statistics:

The following chart and statistics were generated by ESRI ArcGIS 9.3.1, and show the general distribution of the site gamma radiation measurements. The horizontal X axis represents the gamma radiation reading levels in cpm (lowest levels to the left). The vertical Y axis represents the frequency of each gamma radiation level.



 Count:
 1648

 Minimum:
 9139,00000

 Maximum:
 247089,00000

 Sum:
 43749547,00000

 Mean:
 26547,05522

 Median:
 16742,00000

 Standard Deviation:
 31008,04334

Part III Status of Reclamation and Mine Waste

The following information was obtained from the Navajo Abandoned Mine Land Reclamation Program (NAMLRP) Point Features Database:

NAMLRP Status of the mine site: Reclaimed: No Waste Pile onsite: No

NAMLRP Project Number: None

NAMLRP Mine features: 1 Rim Strip / Pit

The following information was obtained from field observations collected during the 2010 site screening:

Provide description and status of all mine sites and features at site. Include all waste piles, adits, pits and other features, and indicate whether they are open, closed, covered, capped, buried or unreclaimed. Indicate approximate size, shape and extent, including description of any reclamation caps. Note condition of all caps.

Observed reclamation work and status

Adits

None

Waste Piles

None

Pits

None

Shafts

None

Other Debris and Mine Features

Pile of petrified wood

Part IV

Site observations and Environs

Observed Structures: list number of and describe human habitation status of structures at the following distances from mine:

0 to 200 feet: None

200 feet to 0.25 mile: None

Observed Public or commercial structure: list and describe all schools, clinics, Chapter Houses, places of business and any other structure used by members of the community at the following distances:

0 to 200 feet: None

200 feet to 0.25 mile: None

Levels measured around the perimeter(s) of the identified structure(s):

None

Observed water sources: list the number and type of wells and surface water sources that are potentially used for human consumption at the following distances from the mine:

0 to 0.25 miles: Berm created to trap water, presumably for livestock, currently dry

0.25 miles to 4 miles: Windmill Well approximately 2 mi SE of the site; Little Colorado River Basin approximately 4 mi E of the site

Sensitive environments: note and describe all sensitive environments located within visible range of the mine site, including: wetlands, endangered species, habitats and approximate locations of sites that may be under protection of the government of the Navajo Nation.

None observed

Known Site History: include information from interviews with Chapter officials and residents. Note information on mine ownership, type of mining operation, period of operation, known amount of production, and any other information as provided.

Paul Huskie No. 20 mine consists of an area of 11,657.57 m². The mine was identified as being operational in 1959. Historical documents showed the operator of the mine as the Domino Mining Company in 1959. While operational, the mine had a total production volume of 23 tons. No other historical information or any additional ownership / lease information was identified in the EPA/AUM database.

Part V Response Action Summary

Summary of Evaluation Factors:

Accessibility:

Was the mine easily accessible to potential human activity? Yes

Radiological Measurements:

Were any gamma radiation measurements collected at the mine greater than two times the site-specific background levels?

Yes

Waste Piles:

Were any unreclaimed waste piles observed at the mine with gamma radiation measurements greater than two times the site-specific background levels? No

Structures:

Were any structures observed within 200 feet of the mine? No

Potential Drinking Water Sources:

Were any potential drinking water sources observed within 4 miles of the mine? Yes

Reclamation:

Was the mine reported to be previously reclaimed, or did the mine appear to be reclaimed?

No

Part VI Photos



Photo 1. Paul Huskie No. 20 mine site



Photo 2. Paul Huskie No. 20 mine site, petrified wood with elevated gamma readings



Photo 3. Paul Huskie No. 20 mine site, area of elevated gamma readings


Name:

Part VII Contacts Reports and Information

Stanley Edison (928) 871-6861


Eugene Esplain (928) 871-7331	
Title or official role (if any) Navajo EPA Superfund Program	
Address PO Box 2946, Window Rock, AZ 86515	
Information provided <u>Lead Regulatory Agency</u>	
Name	
Title or official role (if any)	
Address	
Telephone number	
Information provided	
Name	
Title or official role (if any)	_
Telephone number	_
Information provided	
Name	
Title or official role (if any)	_
Telephone number	_
Information provided	

Figure 1 - Gamma Radiation Measurements, Above Two Times Background
Paul Huskie No. 20 (383)
Cameron Chapter, Navajo Nation




Average background 14,140 cpm

Figure 2 - Gamma Radiation Measurements Paul Huskie No. 20 (383) Cameron Chapter, Navajo Nation



- 0 10,000
- 10,000 15,000
- 15,000 20,000
- 20,000 50,000
- 50,000 100,000
- > 100,000



Gamma survey conducted 11/2010 Measured as counts per minute (cpm)

Average background 14,140 cpm

